



CUSTOMER APPROVAL: _____

ITEM NO.	PART NUMBER	DESCRIPTION	MATERIAL	QTY.
9	ESB1-3-CLAMP	COUNTERBALANCE CLAMP	IRON	1
8	ESB1-A	COUNTERBALANCE	MISC.	1
7	SF240TFXFSS	2" STYLE 40 SPLITFLANGE WITH TTMA FLANGES WITH LONG RADIUS ELBOWS	STAINLESS STEEL	1
6	LEG D: 2LSS-TFXM-81	2" SCHEDULE 40 PIPE WITH TTMA X MALE NPT	STAINLESS STEEL	1
5	LEG C: 2LSS-TFXTF-4 CR	2" SCHEDULE 40 PIPE WITH TTMA AND CONCENTRIC REDUCER	STAINLESS STEEL	1
4	SF370FGXFSS	3" STYLE 70 SPLITFLANGE WITH TTMA, CB MOUNT AND CONCENTRIC REDUCER	STAINLESS STEEL	1
3	BRACE	1/2" STEEL BRACE	STAINLESS STEEL	1
2	LEG A: 3LSS-FGXFG-72" & 72" WITH ELBOW	3" SCHEDULE 40 PIPE WITH 150 lbs. SLIP-ON FLANGES AND ELBOW	STAINLESS STEEL	1
1	SF330FGXFGSS	3" STYLE 30 SPLITFLANGE WITH 150 lbs. FLANGES	STAINLESS STEEL	1

PROPRIETARY AND CONFIDENTIAL
 This drawing is owned by Dixon Valve & Coupling Co. and shall be returned upon demand. It is loaned on condition that it shall not be copied or reproduced or submitted to others without the owners consent. In accepting or any subject to this condition the recipient further agrees that this drawing or any design detail or concept disclosed herein shall not be used in any way detrimental to or in competition with the owner. If the recipient does not agree to the terms of this agreement they shall return this drawing immediately. The information contained in this drawing is subject to change without notice.

DIXON U.S.A.
 THE RIGHT CONNECTION™

TITLE: 3" TO 2" RIGHT HAND LOADING ARM ASSEMBLY
 DATE: 7/2/2018
 MATERIAL: SEE B.O.M.

PART NUMBER: **LA-SH0518206** Rev. A

DO NOT SCALE THIS DRAWING

DIXON
 The Right Connection™
 dixonvalve.com

Loading arms have been designed to work in a set range of motion and calculated to balance the provided equipment. If additional items are installed (such as tie-down chains, drip buckets, valves, vapor hoses etc.) it will adversely affect the balance and range of the loading arm. All loading arms are custom made to order and are not returnable, however Dixon is committed to providing a solution to any unforeseen issue.